




Photographic Schedule of North Wales Hospital




for




Denbighshire County Council,
Smithfield Road,
Denbigh,
LL16 3RJ




Ref: 168119/Chapel Elevation B

Date of Inspection: 28th Sep 2018

Ref	Photo	Comments
1	 A wide-angle, slightly blurred photograph of the chapel building, showing its stone walls, gabled roof, and a small tower. The building is surrounded by trees and a grassy area.	Elevation B. 5 bays
2	 A close-up photograph of the chapel's tower, showing the stone masonry, a wooden door, and the roof structure. The tower is surrounded by trees.	Bay 1
3	 A close-up photograph of the chapel's roof and a wooden door. The roof is made of slate tiles, and there is a noticeable gap or missing slate near the door.	Bay 1 missing slate

4		Bay 2
5		Bay 2 missing slate
6		Bay 3

7		Bay 4
8		Bay 4 left side valley stripped.
9		Bay 5

10		Slate missing bay 4 & 5
11		Right side bay 4
12		Bay 2

13

