

LLWYN CELYN
Stanton
Crucorney Fawr
Gwent
19/17995/DISCON


PHOTOGRAPHIC
SURVEY

PART 1:
THE HOUSE


List of Photographs

- Pl.1: Llwyn Celyn from the south-east, before being swathed in protective scaffolding.
Pl.2: The rear yard of the house in the 1960's.
Pl.3: The scaffolded house from the south-east in 2016.
Pl.4: The house from the south-west.
Pl.5: The lower portion of the east gable and the adjacent rear wing.
Pl.6: The front, or south, wall of the main hall section, porch to the right.
Pl.7: Detail of the porch and main entrance.
Pl.8: The lower part of the east elevation, showing first-floor louver spout.
Pl.9: The east elevation showing junction between original build and later Rear Wing.
Pl.10: Part of the west elevation of the Solar wing.
Pl.11: Detail of limewashed butter-pointed render finish.
Pl.12: The south slope of the roof over the Hall and Service sections, looking west.
Pl.13: The dormer in the south slope of the Hall roof.
Pl.14: The east slope of the roof of the Solar, looking north.
Pl.15: The west slope of the roof of the Solar.
Pl.16: Underside of north slope of roof over the screen's passage at the east end of the Hall.
Pl.17: The east face of the spere truss in the Hall range.
Pl.18: Northern arched brace over the Hall section.
Pl.19: Decorative detail at base of arch-brace in Hall section.
Pl.20: The underside of the south slope of the roof over the Service end.
Pl.21: Part of the Solar roof structure viewed through a broken ceiling.
Pl.22: The southern end of the Solar wing roof, looking south.
Pl.23: Lower wind-bracing on the west slope of the Solar wing roof.
Pl.24: The north gable truss of the Solar wing roof.
Pl.25: The closed truss of the Solar wing roof from the north.
Pl.26: The entrance hall (G2) in 2009.
Pl.27: The entrance hall looking north.
Pl.28: The former services (G1) looking south-east.
Pl.29: The former services looking north-west.
Pl.30: The hall (G3) in 2009, looking south-east.
Pl.31: Initial phase of fireplace explorations in the hall in 2015.
Pl.32: The hall looking south-west.
Pl.33: Detail of the dais bench at the west end of the hall.
Pl.34: Detail of the boxing to the stairs.
Pl.35: Detail of the window to the hall (G3).
Pl.36: Detail of doorway at the southern end of the dais end of the hall (G3).
Pl.37: The north closet in the Solar wing (G4).
Pl.38: View southwards in the ground floor of the Solar wing.
Pl.39: The inner south-east corner of the ground floor room in the Solar (G5).
Pl.40: The north-east corner of G5, showing lobby off the adjacent hall (G3).
Pl.41: The top quarter landing of the stairs.
Pl.42: Looking down the stairs from the top quarter landing.
Pl.43: General view of the stairs from the top landing in the Hall section.
Pl.44: View west from the first-floor 'lobby', F9.
Pl.45: The main first floor corridor, looking east (F7).
Pl.46: The store above the former cross passage (F2).
Pl.47: General view looking north in the east first floor room (F1).
Pl.48: The east side of the timber-framed west wall of the east first floor room (F1).

- Pl.49: The bedroom (F3) above the hall, looking north-west in 2009.
- Pl.50: The first-floor cross-corridor (F10) linking the rooms in the Solar wing, looking north.
- Pl.51: The southern first floor room (F6) in the Solar wing, looking north.
- Pl.52: Detail of ceiling in F6).
- Pl.53: The central first floor room (F5) in the Solar wing, looking north-west in 2009.
- Pl.54: The west wall of the central first floor room in the Solar wing after clearance.
- Pl.55: The south-eastern corner of F5.
- Pl.56: The north first floor room (F4) in the Solar wing, looking west.
- Pl.57: Detail of doorway in the north wall of F4.
- Pl.58: The rear wing from the north-east.
- Pl.59: The east elevation of the Rear Wing (Building A3).
- Pl.60: The west, or courtyard elevation of the Rear Wing, with bread oven lean-to to left.
- Pl.61: The north gable of the Rear Wing.
- Pl.62: The northern end of the ground floor (G8) in the Rear Wing in 2009.
- Pl.63: The exposed fireplace and bread oven in G8).
- Pl.64: The west wall of G8.
- Pl.65: The upper floor of the Rear Wing. Looking south-east.
- Pl.66: The bread oven lean-to attached to the north gable of the Rear Wing.
- Pl.67: The interior of the east end of the bread oven lean-to.



First Floor (and part roof)



Ground Floor

Old Photographs



Pl.1: Llwyn Celyn from the south-east, before being swathed in protective scaffolding.



Pl.2: The rear yard of the house in the 1960's.

The Main House: The Exterior



Pl.3: The scaffolded house from the south-east in 2016.



Pl.4: The house from the south-west.



Pl.5: The lower portion of the east gable and the adjacent rear wing.



Pl.6: The front, or south, wall of the main hall section, porch to the right.



Pl.7: Detail of the porch and main entrance.



Pl.8: The lower part of the east elevation, showing first-floor louver spout.



Pl.9: The east elevation showing junction between original build and later Rear Wing.



Pl.10: Part of the west elevation of the Solar wing.



Pl.11: Detail of limewashed butter-pointed render finish.

The Main House: The Roof



Pl.12: The south slope of the roof over the Hall and Service sections, looking west.



Pl.13: The dormer in the south slope of the Hall roof.



Pl.14: The east slope of the roof of the Solar, looking north.



Pl.15: The west slope of the roof of the Solar.



Pl.16: The underside of the north slope of the roof over the screen's passage at the east end of the Hall.



Pl.17: The east face of the spere truss in the Hall range.



Pl.18: Northern arched brace over the Hall section.



Pl.19: Decorative detail at base of arch-brace in Hall section.



Pl.20: The underside of the south slope of the roof over the Service end.



Pl.21: Part of the Solar roof structure viewed through a broken ceiling.



Pl.22: The southern end of the Solar wing roof, looking south.



Pl.23: Lower wind-bracing on the west slope of the Solar wing roof.



Pl.24: The north gable truss of the Solar wing roof.



Pl.25: The closed truss of the Solar wing roof from the north.

The Main House: The Interior



Pl.26: The entrance hall (G2) in 2009.



Pl.27: The entrance hall looking north.



Pl.28: The former services (G1) looking south-east.



Pl.29: The former services looking north-west.



Pl.30: The hall (G3) in 2009, looking south-east.



Pl.31: Initial phase of fireplace explorations in the hall in 2015.



Pl.32: The hall looking south-west.



Pl.33: Detail of the dais bench at the west end of the hall.



Pl.34: Detail of the boxing to the stairs.



Pl.35: Detail of the window to the hall (G3).



Pl.36: Detail of doorway at the southern end of the dais end of the hall (G3).



Pl.37: The north closet in the Solar wing (G4).



Pl.38: View southwards in the ground floor of the Solar wing.



Pl.39: The inner south-east corner of the ground floor room in the Solar (G5).



Pl.40: The north-east corner of G5, showing lobby off the adjacent hall (G3).



Pl.41: The top quarter landing of the stairs.



Pl.42: Looking down the stairs from the top quarter landing.



Pl.43: General view of the stairs from the top landing in the Hall section.



Pl.44: View west from the first-floor 'lobby', F9.



Pl.45: The main first floor corridor, looking east (F7).



Pl.46: The store above the former cross passage (F2).



Pl.47: General view looking north in the east first floor room (F1).



Pl.48: The east side of the timber-framed west wall of the east first floor room (F1).



Pl.49: The bedroom (F3) above the hall, looking north-west in 2009.



Pl.50: The first-floor cross-corridor (F10) linking the rooms in the Solar wing, looking north.



Pl.51: The southern first floor room (F6) in the Solar wing, looking north.



Pl.52: Detail of ceiling in F6).



Pl.53: The central first floor room (F5) in the Solar wing, looking north-west in 2009.



Pl.54: The west wall of the central first floor room in the Solar wing after clearance.



Pl.55: The south-eastern corner of F5.



Pl.56: The north first floor room (F4) in the Solar wing, looking west.



Pl.57: Detail of doorway in the north wall of F4.

The Rear Wing



Pl.58: The rear wing from the north-east.



Pl.59: The east elevation of the Rear Wing (Building A3).



Pl.60: The west, or courtyard elevation of the Rear Wing, with bread oven lean-to to left.



Pl.61: The north gable of the Rear Wing.



Pl.62: The northern end of the ground floor (G8) in the Rear Wing in 2009.



Pl.63: The exposed fireplace and bread oven in G8).



Pl.64: The west wall of G8.



Pl.65: The upper floor of the Rear Wing. Looking south-east.



Pl.66: The bread oven lean-to attached to the north gable of the Rear Wing.



Pl.67: The interior of the east end of the bread oven lean-to.