

LLWYN CELYN  
Stanton  
Crucorney Fawr  
Gwent  
19/17995/DISCON

PHOTOGRAPHIC  
RECORD  
DURING WORKS  
2016-2018

## **List of Photographs**

- Pl.1: The restored house from the south-east, 2018.  
Pl.2: Blocked first-floor window opening discovered in south gable of Solar, now opened.  
Pl.3: South elevation of the restored house, 2018.  
Pl.4: West elevation of the Solar, 2017.  
Pl.5: The restored house from the north-east, 2018.  
Pl.6: Rear, or north, elevation of the restored house, 2018.  
Pl.7: South slope of roof of Hall Range stripped, 2016.  
Pl.8: Part of the roof over the former hall in the Hall Range, 2016.  
Pl.9: West end of Hall roof, with possible dais canopy traces.  
Pl.10: Surviving section on inner wall-plate of Hall roof, north of main stack.  
Pl.11: Top of spere truss and blocked inserted doorway through it, north of stack.  
Pl.12: Exposed and restored roof over the Hall range, looking east.  
Pl.13: Remodelled roof over the Services, looking north-west, 2016.  
Pl.14: Exposed east gable of the roof over the Services, 2016.  
Pl.15: South-western corner of the Solar roof, stripped ready for repair, 2016.  
Pl.15: Central section of the west slope of the Solar roof.  
Pl.16: The entrance hall (G2), looking north in 2016.  
Pl.17: The entrance hall, looking south, 2016.  
Pl.18: Detail of re-used moulded beam/mullion infilling the spere truss.  
Pl.19: Rear of inserted stack between the spere truss posts.  
Pl.20: Restored heads of paired doorways to the services, 2017.  
Pl.21: The service doors, 2018.  
Pl.22 : The former services looking to the paired screens passage doorways, 2016.  
Pl.23: Dais end of the hall early in the project.  
Pl.24: The hall, looking west to the exposed dais end frame.  
Pl.25: The hall, looking east 2016.  
Pl.26: Evolution of the hall fireplace, Phases I and II.  
Pl.27: The Phase III arrangements, probably of the later-19<sup>th</sup> century.  
Pl.28: The Phase IV mid-20<sup>th</sup> century chimneypiece and later-20<sup>th</sup> century stove of Phase V.  
Pl.29: Doorway found on the inner face of the south wall near the dais end of the hall, 2017.  
Pl.30: The doorway.  
Pl.31: Detail of blocking of the top of the doorway.  
Pl.32: The doorway once the main infill had been removed.  
Pl.33: The doorway as restored and expressed, 2018.  
Pl.34: Remains of inserted blocked doorway for stairs through north side of spere truss.  
Pl.35: Present almost identical doorway for the present stair landing through south side.  
Pl.36: Upper portion of the Hall section during repairs, looking east, side corridor removed.  
Pl.37: Western portion of the Hall section at first-floor level after removal of cross-corridor.  
Pl.38: Chamber over hall prior to removal of partitions.  
Pl.39: West end of first-floor over hall after removal of corridors.  
Pl.40: Bedroom over services after clearance but in advance of repairs.  
Pl.41: Northern ground-floor room in solar wing, looking east to the hall.  
Pl.42: South-western corner of the eastern Solar room, 2016.  
Pl.43: Ground-floor of solar, looking north-west after removal of inserted partitions, 2017.  
Pl.44: South end of the south ground-floor room in the solar, 2017.  
Pl.45: East side of the south ground floor room in the solar, the door lobby led to the hall.  
Pl.46: North wall of south ground-floor room of the solar prior to removal, 2016.  
Pl.47: The restored cross-frame between the two ground-floor solar rooms, 2018.


- Pl.48: Exposed inner masonry of the western first-floor wall of the solar, south end., 2017.
- Pl.49: Exposed inner masonry of the western first-floor room of the solar, middle, 2017.
- Pl.50: Exposed inner masonry of the western first-floor room of the solar, north end, 2017.
- Pl.51: Inserted fireplace in the west wall of the solar at first-floor level with incised head.
- Pl.52: Norther first-floor room in solar, looking east into the hall range, 2017.
- Pl.53: Western end of cross-frame at first-floor level in the solar range.
- Pl.54: South end of first-floor solar room, with restored window opening in gable end, 2017.
- Pl.55: Work in progress on north gable end of Rear Wing.
- Pl.56: Rediscovered mullioned window in north gable end of Rear Wing.
- Pl.57: East roof slope of Rear Wing after de-slating, 2017.
- Pl.58: South gable of Rear Wing roof, built up from north wall of the original house.
- Pl.59: Roof truss of the Rear Wing.
- Pl.60: Beginning of internal strip of north gable wall (G8) in the Rear Wing, 2017.
- Pl.61: Stripping out work continuing, ground-floor, looking north.
- Pl.62: Upper floor or loft of Rear Wing, looking south towards the original house.
- Pl.63: Upper floor of Rear Wing looking north to stack and gable.
- Pl.64: Dormer gable in east slope of the roof of the Rear Wing.
- Pl.65: Rear of farmhouse in 2017, with Apple Store (Building C) to right.
- Pl.66: Restored front of Apple Store, 2017.
- Pl.67: Restored and raised West Barn or Stable, Building E, from the east.
- Pl.68: Restored Stable from the north; note raised gable.
- Pl.69: South side of Beast House (Building F) during works, Shelter Shed largely removed.
- Pl.70: The Beast House from the north-west, 2016, works in progress on roof.
- Pl.71: South slope of Beast House roof after being stripped.
- Pl.72: Beast House roof, internal view prior to removal of covering.
- Pl.73: Northern bay of Beast House prior to restoration.
- Pl.74: View west in Beast House to revetment wall and boarded cross frame, 2016.
- Pl.75: Internal view of the east gable frame of the Beast House at ground-floor level, 2016.
- Pl.76: Detail of internal reveal of east gable window of the Beast House.
- Pl.77: Restored Beast House and rebuilt Shelter Shed (Building G) from the south-west.
- Pl.78: Restored Beast House from the north-west, 2017.
- Pl.79: East gable of restored Beast House.
- Pl.80: The restored interior of the Beast House.
- Pl.81: The rebuilt Shelter Shed (Building G).
- Pl.82: Re-set truss and part frame of earlier structure of Shelter Shed.
- Pl.83: View of the Corn Drier (I, left) and site of Piggery (Building H) from the north-west.
- Pl.84: General view westwards towards the restored Corn Drier.
- Pl.85: Threshing Barn (Building J) from the east under restoration.
- Pl.86: Stabilisation works within the Threshing Barn, looking north.
- Pl.87: The north gable of the restored Threshing Barn.
- Pl.88: View of the eastern farm buildings from the east.

# PART 1: THE HOUSE





First Floor (and part roof) plan showing photograph locations.



Ground Floor plan, showing photograph locations.



Pl.1: The restored house from the south-east, 2018.



Pl.2: Blocked first-floor window opening discovered in south gable of Solar, now opened.





Pl.3: South elevation of the restored house, 2018.



Pl.4: West elevation of the Solar, 2017.





Pl.5: The restored house from the north-east, 2018.



Pl.6: Rear, or north, elevation of the restored house, 2018.





Pl.7: South slope of roof of Hall Range stripped, 2016.



Pl.8: Part of the roof over the former hall in the Hall Range, 2016.





Pl.9: West end of Hall roof, with possible dais canopy traces.



Pl.10: Surviving section on inner wall-plate of Hall roof, north of main stack.



Pl.11: Top of spere truss and blocked inserted doorway through it, north of stack.



Pl.12: Exposed and restored roof over the Hall range, looking east.





Pl.13: Remodelled roof over the Services, looking north-west, 2016.



Pl.14: Exposed east gable of the roof over the Services, 2016.





Pl.15: South-western corner of the Solar roof, stripped ready for repair, 2016.



Pl.15: Central section of the west slope of the Solar roof.





Pl.16: The entrance hall (G2), looking north in 2016.



Pl.17: The entrance hall, looking south, 2016.



Pl.18: Detail of re-used moulded beam/mullion infilling the spere truss.



Pl.19: Rear of inserted stack between the spere truss posts.





Pl.20: Restored heads of paired doorways to the services, 2017.



Pl.21: The service doors, 2018.



Pl.22 : The former services looking to the paired screens passage doorways, 2016.



Pl.23: Dais end of the hall early in the project.





Pl.24: The hall, looking west to the exposed dais end frame.



Pl.25: The hall, looking east 2016.



Pl.26: Evolution of the hall fireplace – phases I and II, the original open fireplace of the 17<sup>th</sup> century with the inserted bread oven to the right; other remnants belong to Phase III.



Pl.27: The Phase III arrangements, probably of the later-19<sup>th</sup> century.



Pl.28: The Phase IV mid-20<sup>th</sup> century chimneypiece and later-20<sup>th</sup> century stove of Phase V.





Pl.29: Doorway found on the inner face of the south wall near the dais end of the hall, 2017.



Pl.30: The doorway.



Pl.31: Detail of blocking of the top of the doorway.





Pl.32: The doorway once the main infill had been removed.



Pl.33: The doorway as restored and expressed, 2018.



Pl.34: Remains of inserted blocked doorway for stairs through north side of spere truss.



Pl.35: Present almost identical doorway for the present stair landing through south side.



Pl.36: Upper portion of the Hall section during repairs, looking east, side corridor removed.



Pl.37: Western portion of the Hall section at first-floor level after removal of cross-corridor.





Pl.38: Chamber over hall prior to removal of partitions.



Pl.39: West end of first-floor over hall after removal of corridors.



Pl.40: Bedroom over services after clearance but in advance of repairs.



Pl.41: Northern ground-floor room in solar wing, looking east to the hall.





Pl.42: South-western corner of the northern Solar room, 2016.



Pl.43: Ground-floor of solar, looking north-west after removal of inserted partitions, 2017.





Pl.44: South end of the south ground-floor room in the solar, 2017.



Pl.45: East side of the south ground floor room in the solar, the door lobby led to the hall.



Pl.46: North wall of south ground-floor room of the solar prior to removal, 2016.



Pl.47: The restored cross-frame between the two ground-floor solar rooms, 2018.





Pl.48: Exposed inner masonry of the western first-floor wall of the solar, south end., 2017.



Pl.49: Exposed inner masonry of the western first-floor room of the solar, middle, 2017.



Pl.50: Exposed inner masonry of the western first-floor room of the solar, north end, 2017.



Pl.51: Exposed early inserted fireplace in the west wall of the solar at first-floor level with incised head.





Pl.52: Norther first-floor room in solar, looking east into the hall range, 2017.



Pl.53: Western end of cross-frame at first-floor level in the solar range, and position of the primary doorway through it – replaced by one at opposite end.



Pl.54: South end of first-floor solar room, with restored window opening in gable end, 2017.



Pl.55: Work in progress on north gable end of the Rear Wing.





Pl.56: Rediscovered mullioned window in north gable end of the Rear Wing.



Pl.57: East roof slope of Rear Wing after de-slating, 2017.





Pl.58: South gable of Rear Wing roof, built up from north wall of the original house.



Pl.59: Roof truss of the Rear Wing.





Pl.60: Beginning of internal strip of north gable wall (G8) in the Rear Wing, 2017.



Pl.61: Stripping out work continuing, ground-floor, looking north.





Pl.62: Upper floor or loft of Rear Wing, looking south towards the original house.



Pl.63: Upper floor of Rear Wing looking north to stack and gable.






Pl.64: Dormer gable in east slope of the roof of the Rear Wing.

# PART 2: THE FARM BUILDINGS





Outline Site Plan and Photo locations.



Pl.65: Rear of farmhouse in 2017, with Apple Store (Building C) to right.



Pl.66: Restored front of Apple Store, 2017.





Pl.67: Restored and raised West Barn or Stable, Building E, from the east.



Pl.68: Restored Stable from the north; note raised gable.





Pl.69: South side of Beast House (Building F) during works, Shelter Shed largely removed.



Pl.70: The Beast House from the north-west, 2016, works in progress on roof.





Pl.71: South slope of Beast House roof after being stripped.



Pl.72: Beast House roof, internal view prior to removal of covering.





Pl.73: Northern bay of Beast House prior to restoration.



Pl.74: View west in Beast House to revetment wall and boarded cross frame, 2016.





Pl.75: Internal view of the east gable frame of the Beast House at ground-floor level, 2016.



Pl.76: Detail of internal reveal of east gable window of the Beast House.





Pl.77: Restored Beast House and rebuilt Shelter Shed (Building G) from the south-west.



Pl.78: Restored Beast House from the north-west, 2017.





Pl.79: East gable of restored Beast House.



Pl.80: The restored interior of the Beast House.



Pl.81: The rebuilt Shelter Shed (Building G).



Pl.82: Re-set truss and part frame of earlier structure of Shelter Shed.





Pl.83: View of the Corn Drier (I, left) and site of Piggery (Building H) from the north-west.



Pl.84: General view westwards towards the restored Corn Drier.





Pl.85: Threshing Barn (Building J) from the east under restoration.



Pl.86: Stabilisation works within the Threshing Barn, looking north.





Pl.87: The north gable of the restored Threshing Barn.



Pl.88: View of the eastern farm buildings from the east.