Former HM Stanley Hospital Photographic Survey Undertaken 12/11/2014 Between David Wilkinson & Kirsty Henderson FINANCE BUILDING

Typical Window (1 & 2)



Typical Door With Fanlight (3)



Fan Light Mechanism (4)




Terracotta Cill To Window (5)



Internal Cupboard (6)



Parquet Floor (7)




Architrave Blocks (8)



Stairs (9 & 10)





Stair Tread Profile (11)



External Doors (12)



Corridor (13)







Door Rose & Handle (15)

Stairs (16)





Typical First Floor Window (17)



5 Panel Door (19)



Typical Floor Boards (18)



Original Skirting (20)



Parquet Flooring (21)


Built in Cupboard (22)





Stairs (23)

Stair Hand Rail (24)





Finance Building Externals (25 – 27)

(25) (26)





(27)



OUT-PATIENTS BUILDING

Back Door (1)



External Gutter (3)



External Gutter (2)



Gutter Brackets (4)



Outpatients Building Externals (5)



Outpatients building Externals (6)

