

APPENDIX 2

PHOTOGRAPHIC ARCHIVE

1	Workhouse	View from the southwest
2		Lluesty frontage, view from the north
3		View from the northeast
4		Front entrance off Old Chester Road
5	1902 Nurses' Residence	Classical façade to Old Chester Road
6		Classical façade, view from north
7		Buttress detail
8		Open pedimented porch
9		1902 rear window detail
10		Rear elevation of Nurses' Residence, view across Chapel Yard
11		View across Chapel Yard towards the rear of the Nurses' Residence and the 1884 Chapel
12	Chapel Yard	Entrance off Brynford Road into Chapel Yard
13		View from the north across Chapel Yard
14		East elevation of the north wing of the workhouse, viewed from Chapel Yard
15	Workhouse	Cross wing viewed from the north
16	Workhouse & Bell Yard	Cross wing, as above, view from the west from the northwest yard, known as the Bell Yard
17		West elevation of the Workhouse north wing, view across the Bell Yard
18		Bell Yard and the north elevation of the west wing
19	Workhouse	Cross wing of the Workhouse west wing, north and west elevation
20		As above, south and west elevation with modern buildings & chimney in the background
21		Workhouse West and South wings extending from the central octagon
22		Central Octagon
23		Toilet / bathroom addition to the west elevation of the Workhouse south wing
24		Cross wing of the Workhouse south wing
25		Workhouse viewed from the south
26	Pump Yard	View over the Pump Yard towards the east wing that connects the Octagon to the Administration Block
27		Viewed from north towards the single storey building with Pump outside
28		Cast iron pump
29		South cross wing east elevation from Pump Yard
30		East elevation of the Workhouse south wing extending south from the Octagon
31		Pump Yard with lean-to additions to the 'curtain wall'
32	Vagrants' Wards complex	Hospital works department, part of the former Vagrants' Wards complex
33		Workshop entrance
34		Workshop door
35	Assistant Master's House	Former hospital Pharmacy building, previously the Assistant Master's House
36	Pump Yard	Enclosing east wall connecting the main Administration Block to the Assistant Master's House
37	1884 Chapel	1884 Chapel designed by John Douglas, east elevation
38		Chapel west elevation
39		Chapel east window
40		Chapel south door
41	Chapel Yard	Pump
42	Workhouse	Window sample
43		View from the southwest towards the modern additions to the Workhouse
44		1838-40 Workhouse Administration Block entrance hall
45	Administration Block	Fanlight lattice detail
46		Entrance Hall north doors
47		Main hall panelled door

48		Admin, panelled door to front office
49		Front office fireplace
50		Admin. ground to first floor staircase
51	Workhouse	First floor corridor from Admin. to the Octagon
52		Workhouse, small room sample
53		Ward 6B, Workhouse second floor, view from the east
54		Ward 6A, Workhouse second floor, view from the south
55		Workhouse first floor door sample
56		Ward 6B, second floor former fireplace
57		Towel rail fitting
58		Radiator sample
59	Octagon	Top / third floor; handrail at top of wooden dog-leg steps
60		Third floor water tanks, view from south
61		Third floor southwest door
62	Workhouse	North wing, ground floor
63		Workhouse north wing
64		Workhouse flat staircase
65		Stone steps rear of Workhouse Admin. Block
66		As above
67	Nurses' Residence	Rear entrance to Nurses' Residence
68		Nurses' Residence door sample
69		-
70		Staircase
71		Staircase side elevation
72		Nurses' Residence function room, view from the south
73		as above, view from the north
74	1913 Infirmary	Infirmary viewed from Old Chester Road
75		Central Block with 1913 datestone
76		Front / west elevation, view from the northwest
77		North side Octagonal Bay
78		Front / west entrance
79		North elevation
80		South elevation
81		Foundation stone
82		1913 date stone
83		View from the northeast
84		Staircase from ground to first floor
85		As above
86		First floor corridor
87		First floor door sample
88		First floor room
89		Second floor corridor
90		Second floor roof access
91		First floor lift access
92		First floor north ward
93		First floor south ward
94		First floor partition between main ward & single ward in the octagonal bay
95		Towel rail sample
96	Stores / Air raid shelters	Single storey building / stores located south of the Infirmary
97		Single storey building / stores located northwest of the Infirmary
98	Adjacent land	Rising land to the west of the Workhouse, included in development proposals. View from the southeast
99		As above, view from the northeast
100		View down Brynford Road towards the Tank recorded on Fig. 1 & earthworks remains of spoil tips resulting from leadmining
101		Spoil tips viewed from the northeast