



Lower Berse Farm, Wrecsam, ym 1970


Lower Berse Farm, Wrexham in 1970



DI2011_0577 NPRN 27477

Chwth: Ystafell fyw Lower Berse Farm. Er i'r llun gael ei dynnu ym 1970, mae'r addurno'n adlewyrchu arddulliau a phatrymau a oedd yn boblogaidd o ddechrau'r 1900au ymlaen.

Left: The living room at Lower Berse Farm. Although the photograph was taken in 1970, the decoration reflects styles and patterns that were popular from the early 1900s onwards.



DI2011_0571 NPRN 27477

Chwth: Pan ychwanegwyd llawr uchaf at yr adeilad, cuddiwyd cyplau cerfiedig y to o'r golwg. Gallant roi gwybodaeth bwysig am ddyddiad yr adeilad ac am ddatblygiad pensaernïaeth draddodiadol Cymru.

Left: When an upper floor was inserted into the building, the carved roof trusses were hidden from view. These can provide important information on the date of the building and the development of Welsh traditional architecture.

Ym 1970 fe ymweodd y Comisiwn Brenhinol â Lower Berse Farm ger Wrecsam i ymchwilio i hanes yr adeilad a rhoi cyngor i'r perchnogion am fod arnynt eisiau moderneiddio'r llawr uchaf. Cawsai tŷ neuadd canoloesol ei guddio adeg ailgodi'r adeilad ym 1873. Gwnaed lluniadau ohono a thynnwyd ffotograffau i'w hadneuo yn yr archif.


In 1970 the Royal Commission visited Lower Berse Farm near Wrexham to investigate the history of the building and provide advice to the owners, who wanted to modernise the upper floor. There was a medieval hall house hidden amid a rebuild of 1873. Drawings were made and photographs taken for deposition in the archive.



DI2011_0572 NPRN 27477

Chwth: Cerfiwyd Canopi Esgynlawn Lower Berse Farm yn gelydd ac mae'n amlwg ei fod yn arwydd o statws. O dano yr eisteddai perchenog yr eiddo i fwyt a chynnal busnes wrth ei fwrrd.

Left: The Dais Canopy at Lower Berse Farm, under which the owner of the property sat to eat and conduct business at his table is deftly carved, and is a clear status symbol.



DI2011_0578 NPRN 27477

Chwth: Gwnaed y lluniad hwn i ddangos coed y to mewn perthynas â gweddill yr adeiladwaith.

Left: This drawing was made to show the roof timbers in relation to the rest of the building structure.

Isod: Un o'r miloedd o adeiladau y mae'r Comisiwn wedi'u harolygu yw Lower Berse Farm. Gall y cyhoedd grychu'r cofnodion hynny yn swyddfa'r Comisiwn Brenhinol yn Aberystwyth a hefyd, fwyfwy, ar-lein drwy www.coflein.gov.uk

Below: Lower Berse Farm is just one of thousands of buildings which the Commission has surveyed. The public can access these records at the Royal Commission's office in Aberystwyth, increasingly, online through www.coflein.gov.uk



DI2011_0576 NPRN 27477