

SITE NAME: Loreto Convent, Llandudno, Conwy				NGR: SH772821	
Format	Digital	Photographer	Alvaro Mora-Ottomano	Date	4-5-15
Frame	Building	Description	Direction	Plate	
1	A and B	General view from car park	NW	1	
2	B	Walkway tower and gallery	NW	33	
3	B	Underneath walkway	W		
4	B	Walkway linking to Building A	E	34	
5	B	Walkway linking to Building A	NE		
6	A	General view	NE		
7	A	General view	NE	2	
8	A	South and west elevations	NE	3	
9	A	West elevation	E	4	
10	A	West elevation	E	5	
11	A	North elevation	S	6	
12	A	North elevation	SW		
13	A	North elevation	S		
14	A	North elevation	SE		
15	A	Detail of chimney stack	S	7	
16	A	Detail of chimney stack	S		
17	A	Detail of chimney stack	S		
18	A	East elevation	SW	8	
19	A	Detail of semi-circular arched window	W	9	
20	A	Detail of semi-circular arched window	W		
21	A	Detail of semi-circular arched window	W		
22	A	Detail of semi-circular arched window	W		
23	A and B	South elevation with walkway	W		
24	A and B	South elevation with walkway	W	10	
25	B	Walkway	SW	32	
26	B	North elevation main structure	SE	31	
27	B	North elevation main structure	SE		
28	B	North elevation main structure	SW		
29	A	South elevation with conservatory	NW		
30	B	Main structure and tower walkway	N	29	
31	B	Main structure and tower walkway	N		
32	B	South elevation	NW	30	
33	B	First floor's corridor	W		
34	B	First floor's corridor	W	38	
35	B	First floor's corridor	S		
36	B	First floor's corridor	S	36	
37	B	Inside western walkway gallery	E	35	
38	B	Inside western walkway gallery	E		
39	B	Inside walkway linking Building A	N	37	
40	B	Inside walkway linking Building A	N		
41	A	Ground floor's doorway	N	11	
42	A	Ground floor's corridor	E		
43	A	Ground floor's corridor	E	12	
44	A	Office door	NE		
45	A	Meeting room	E		
46	A	Meeting room	E		
47	A	Meeting room	E	14	
48	A	Meeting room	NE	13	
49	A	Conservatory	E	17	
50	A	Conservatory	E		

SITE NAME: Loreto Convent, Llandudno, Conwy				NGR: SH772821	
Format	Digital	Photographer	Alvaro Mora-Ottomano	Date	4-5-15
Frame	Building	Description	Direction	Plate	
51	A	Small north-western meeting room	NW	15	
52	A	Kitchen	N	16	
53	A	Kitchen	N		
54	A	Lobby	W	19	
55	A	Sash along corridor	SE	18	
56	A	Sash along corridor	SE		
57	A	Sash along corridor	SW		
58	A	Staircase	E		
59	A	Staircase	SE		
60	A	Staircase	SE	20	
61	A	Staircase	S	21	
62	A	Roof truss	E		
63	A	Roof truss	E	28	
64	A	First floor's corridor	E	22	
65	A	First floor's corridor	E		
66	A	First floor's lobby	N	23	
67	A	Lavatory door	SW	24	
68	A	Detail of lock	SW	25	
69	A	Detail of lock	E		
70	A	Bedrooms	NE	26	
71	A	Bedrooms	N		
72	A	Bedrooms	SW		
73	A	Bedrooms	SW		
74	A	First floor's corridor	W	27	
75	C	West and south elevations	NE		
76	C	West and south elevations	NE	39	
77	C	East and south elevations	NW	41	
78	C	Doorway	W		
79	C	East elevation	W	43	
80	C	East elevation	W	42	
81	C	East elevation	W		
82	D and E	West side of walkway to Loreto Convent building	E		
83	D and E	West side of walkway to Loreto Convent building	E		
84	E	Lavatory block	SW	68	
85	E	Lavatory block	SW		
86	E	Lavatory block and lift tower	W	67	
87	E	Lavatory block and lift tower	W		
88	D	General view	NW	55	
89	D	South elevation	N		
90	D	South elevation	N	56	
91	D	South elevation	NW	57	
92	D	Rear north elevation	SW	59	
93	D	East gable wall	W	58	
94	D	North elevation with walkway staircase	W	60	
95	D	Detail of slated roof	E		
96	D	External balcony of walkway to Loreto building	N	61	
97	C	Roof and east elevation	W		
98	C	Roof and east elevation	W		
99	C	Roof and east elevation	W		
100	C	Roof and east elevation	W		

SITE NAME: Loreto Convent, Llandudno, Conwy				NGR: SH772821	
Format	Digital	Photographer	Alvaro Mora-Ottomano	Date	4-5-15
Frame	Building	Description	Direction	Plate	
101	C	Roof and east elevation	NW		
102	C	West elevation	E		
103	C	West elevation	NE		
104	C	Large porch for walkway	N	40	
105	C	Large porch for walkway	N		
106	C	Staircase inside large porch	W		
107	C	Staircase inside large porch	W	44	
108	C	Inside garage	W	45	
109	C	Ground floor with inserted internal doorway	SE		
110	C	Ground floor with inserted internal doorway	SE	46	
111	C	Partially truncated chimney breast	NE	47	
112	C	Inserted staircase	SE	48	
113	C	Inserted staircase	SE		
114	C	First floor's corridor	S		
115	C	First floor's corridor	N	49	
116	C	First floor's bedroom	NW	50	
117	C	First floor's bedroom	NW		
118	C	Roof structure	S		
119	C	Roof structure	S	53	
120	C	Roof structure	S	54	
121	C	First floor's bedroom	NE	52	
122	C	First floor's bedroom	NW		
123	C	First floor's bedroom	NW	51	
124	D	Inside walkway to the Loreto building	SE	62	
125	D	Inside walkway to the Loreto building	SE		
126	D	First floor's corridor	E	63	
127	D	First floor's bedroom	SE	64	
128	D	Staircase to the ground floor	S	65	
129	D	Ground floor's bedroom	SE	66	
130	E	Lift tower	W		
131	E	Lift tower	W		