
Insole Court

Photographic record - externals to house



27th November 2015




ANDREW SCOTT LTD. 05 DEC 2014 Do not scale from this drawing. All dimensions are to be verified on site before proceeding with the work. DRAWING STATUS ISSUED FOR CONSTRUCTION All dimensions are in millimeters unless note
Purcell shall be northed in writing of any disc

Key Plan
not to scale. JOB NUMBER 233111 DRAWING NO. 102



Insole Court – Externals House - 151127



003 – area boarded up for safety reasons



004 – area of undamaged footpath



013 – blocked gully and tarmac area



032- damage to head over main entrance



053 – footpath in front of door



055 – footpath outside of office area



058 – footpath badly repaired



060 – footpath to outside of office



075 – gully blocked and damaged footpath



076 – high level damage to stone work



086 – Left hand column to porch



090 – paving damage



091 – paving lifted and damaged



092 – paving lifting



093 – paving to door



105 – poor repairs to tarmac foot path



106 – poor repairs to tarmac



107 – poor repairs to footpath



159 – tarmac damage in front of commemorative bench



161 - tarmac damage to footpath to swiss wing



162 – tarmac damage to right hand side of steps



163 – tarmac damage to left hand side of steps



170 – tarmac to side of house has been replaced



171- tree roots penetrating foot path



174 – wall damage to swiss wing area