

**PHOTOGRAPHIC SURVEY**  
**PENCERRIG PELLAF**  
**FFORD UCHAF**  
**HARLECH**  
**GWYNEDD**  
**PLANNING APPLICATION NO: NP5/61/LB446A**

**Photographer:** Kimberley Urch  
**Date:** Photos taken on 16<sup>th</sup> February 2019 where marked on the photograph  
All others taken in 2017

**NOTES**

**Pigsty**

The roof of the pigsty has fallen in above the North side and the North section of the pigsty is inaccessible due to debris and overgrowth. The interior of the middle section is also not safe to enter further than from where the submitted photos have been taken.

**Barn**

Barn interior first floor has largely collapsed and access to first floor areas is limited due to safety.

**PHOTOS**

- 001 Pigsty – Exterior West elevation
- 002 Pigsty – Exterior South elevation
- 003 Pigsty – Exterior East elevation A
- 004 Pigsty – Exterior Roof
- 005 Pigsty – Exterior East elevation B
- 006 Pigsty – Exterior North elevation
- 007 Pigsty – Exterior North elevation window aperture
- 008 Pigsty – Exterior North elevation drain aperture
- 009 Pigsty – Exterior East elevation C
- 010 Pigsty – Entrance on East elevation to North section of pigsty
- 011 Pigsty – East Elevation D
- 012 Pigsty – West elevation entrance to South section of pigsty
- 013 Pigsty – Interior South section South elevation
- 014 Pigsty – Interior South section West elevation
- 015 Pigsty – Interior South section Roof
- 016 Pigsty – Entrance to middle section of pigsty
- 017 Pigsty – Interior middle section East elevation
- 018 Pigsty – Interior middle section North elevation
  
- 019 Garage – Exterior situation
- 020 Garage – Exterior West elevation A
- 021 Garage – Exterior West elevation B
- 022 Garage – Steps up from garden to Garage area
- 023 Garage – Exterior North elevation
- 024 Garage – Interior East elevation
- 025 Garage – Interior West elevation
- 026 Garage – Interior North elevation

- 027 Barn – Exterior West elevation A
- 028 House – Exterior West elevation A
- 029 Garden – Front garden area looking South
- 030 House – Exterior West elevation B
- 031 House – Exterior West elevation C
- 032 House – Exterior West elevation D
- 033 Garden Wall feature
- 034 House – Front door
- 035 House – Across front of house Northwards
- 036 House – Exterior South elevation A
- 037 House – Exterior South elevation B
- 038 House – Exterior South elevation C
- 039 House – Front Gate
- 040 Garden – Front Garden view
- 041 Barn – Exterior North elevation
- 042 Barn – Exterior North elevation and driveway
- 043 Barn – Exterior North elevation and rear of barn
- 044 Barn – Rear view of barn from driveway
- 045 Barn – Exterior East elevation and roof
- 046 Barn – rear garden and driveway A
- 047 Garden – rear garden entrance
- 048 Barn – rear garden and driveway B
- 049 House – Exterior East elevation A
- 050 House – Exterior East elevation B
- 051 House – Exterior East elevation C
- 052 House – Exterior East elevation D
- 053 House – Exterior East elevation and roof
- 054 House – East side of roof
- 055 House – Exterior South elevation D
- 056 Barn – Exterior West elevation B
- 057 Barn – Exterior Flagstones entrance
- 058 Barn – Exterior Upper window
- 059 Barn – Exterior Lower window
- 060 Barn – Interior West elevation
- 061 Barn – Interior East elevation
- 062 Barn – Interior North elevation
- 063 Barn – Interior floor
- 064 Barn – Interior fireplace A
- 065 Barn – Interior fireplace B
- 066 Barn – Interior fireplace bread oven A
- 067 Barn – Interior fireplace bread oven B
- 068 Barn – Interior fireplace stone mantel
- 069 Barn – Interior South elevation
- 070 Barn – Interior portion of ceiling
- 071 Barn – Interior ceiling above entrance
- 072 Barn - Interior doorway flagstone floor
- 073 Barn – Interior ceiling beam and hooks
- 074 Barn – Interior ceiling above fireplace
- 075 Barn – Interior first floor remains of partition
- 076 Barn – Interior first floor South elevation West front section
- 077 Barn – Interior first floor West elevation A
- 078 Barn – Interior first floor West elevation B

- 079 Barn – Interior first floor roof West front section
- 080 Barn – Interior first floor South elevation East rear section
- 081 Barn – Interior first floor roof East rear section
- 082 Barn – Interior first floor North elevation
- 083 House – Exterior view up hill from lower garden
  
- 084 House – Interior living room North elevation
- 085 House – Interior living room West elevation
- 086 House – Interior living room East elevation
- 087 House – Interior living room ceiling
- 088 House – Interior living room window
- 089 House – Interior living room South elevation
- 090 House – Interior living room cupboard feature slate
- 091 House – Interior living room cupboard feature wood
- 092 House – Interior living room fireplace stone mantel
  
- 093 House – Interior hallway
- 094 House – Interior hallway stairs A
- 095 House – Interior hallway bannisters
- 096 House – Interior hallway Parlour entrance
- 097 House – Interior hallway floor
- 098 House – Interior hallway stairs B
- 099 House – Interior hallway stairs C
- 100 House – Interior hallway front doorway A
- 101 House – Interior hallway front doorway B
- 102 House – Porch slate feature
  
- 103 House – Interior Parlour South elevation
- 104 House – Interior Parlour West elevation
- 105 House – Interior Parlour North elevation
- 106 House – Interior Parlour East elevation
- 107 House – Interior Parlour floor
- 108 House – Interior Parlour cupboard feature upper
- 109 House – Interior Parlour cupboard feature lower
- 110 House – Interior Parlour Windowsill
  
- 111 House – Interior hallway kitchen entrance
- 112 House – Interior kitchen East elevation
- 113 House – Interior kitchen ceiling
- 114 House – Interior kitchen window
- 115 House – Interior kitchen windowsill
- 116 House – Interior kitchen North elevation
- 117 House – Interior kitchen South elevation
- 118 House – Interior kitchen West elevation
  
- 119 House – Interior first floor landing North elevation
- 120 House – Interior first floor landing East elevation
- 121 House – Interior first floor landing Windowsill
- 122 House – Interior first floor landing West elevation
- 123 House – Interior first floor landing South elevation
- 124 House – Interior first floor landing wooden ledge

- 125 House – Interior bathroom South elevation
- 126 House – Interior bathroom windowsill
- 127 House – Interior bathroom East elevation
- 128 House – Interior bathroom ceiling beam
- 129 House – Interior bathroom West elevation
- 130 House – Interior bathroom ceiling
- 131 House – Interior bathroom floor
  
- 132 House – Interior bedroom 2 South elevation
- 133 House – Interior bedroom 2 West elevation
- 134 House – Interior bedroom 2 North elevation
- 135 House – Interior bedroom 2 East elevationn
- 136 House – Interior bedroom 2 Windowsill
- 137 House – Interior bedroom 2 cupboard
- 138 House – Interior bedroom 2 ceiling
- 139 House – Interior bedroom 2 floor
  
- 140 House – Interior bedroom 3 West elevation
- 141 House – Interior bedroom 3 South elevation
- 142 House – Interior bedroom 3 North elevation
- 143 House – Interior bedroom 3 ceiling
- 144 House – Interior bedroom 3 floor
  
- 145 House – Interior bedroom 1 West elevation
- 146 House – Interior bedroom 1 North elevation A
- 147 House – Interior bedroom 1 North elevation B
- 148 House – Interior bedroom 1 East elevation
- 149 House – Interior bedroom 1 windowsill
- 150 House – Interior bedroom 1 South elevation
- 151 House – Interior bedroom 1 fireplace hearthstone
  
- 152 House – Interior attic 1 South elevation
- 153 House – Interior attic 1 East elevation
- 154 House – Interior attic 1 West elevation
- 155 House – Interior attic 1 North elevation
- 156 House – Interior attic 1 historic door partially sealed by floor
  
- 157 House – Interior attic 2 North elevation
- 158 House – Interior attic 2 North elevation and ceiling
- 159 House – Interior attic 2 West elevation
- 160 House – Interior attic 2 South elevation
- 161 House – Interior attic 2 East elevation
  
- 162 House – Interior attic 3 South elevation
- 163 House – Interior attic 3 East elevation
- 164 House – Interior attic 3 North elevation
  
- 165 House – Exterior view looking North West from adjoining field