

MAIN HOUSE

- ① NORTH EAST FACING EXTERIOR WALL OF HOUSE. IRREGULAR STONE BLOCKS. CENTRAL DOOR WITH A WINDOW EITHER SIDE. STONE BLOCKS OF VARYING SIZES RANGING FROM 120cm x 7cm UP TO 122cm x 50cm. DOORWAY W 83cm x H 176cm. EASTERN WINDOW: W 53cm x H 76cm. WESTERN WINDOW: W 59cm x H 90cm. WESTERN WINDOW BEEN RECENTLY REBUILT. CAN BE SEEN FROM STONE LINTEL ABOVE WINDOWS + DOOR THOUGHT TO BE ORIGINAL, WHILST INTERIOR LINTELS HAVE BEEN REPLACED (PERS. COMM. MEDWIN). THICKNESS OF WALL AT DOOR W 82cm. PHOTO NUMBERS: 494-6.
- ② NORTH WEST GABLE END EXTERIOR, WITH NO OPENINGS. CONSTRUCTED OF IRREGULAR BLOCKS (SEE NOTE 1). UP TO HEIGHT OF EXTERIOR WALL, SMALLER STONES. JUTTED OUT STONE IN NEW CENTRE OF WALL: 17cm. 140cm ABOVE GROUND. PHOTO NUMBERS: 497-9. JUTS OUT THIS MUCH.
- ③ SOUTH WEST FACING REAR WALL OF STRUCTURE. IT HAS SINGLE WINDOW WHICH IS OFFSET TO EAST, W 52cm x H 45cm. SOUTH END CORNER OF WALL HAS BEEN DEMOLISHED TO CREATE SHEEP DIP (PERS COMM. MEDWIN). PART OF TOP OF WALL HAS BEEN REBUILT. PHOTO NUMBERS: 501-2. PART OF EXTERIOR WALLS BOWS INWARDS, POSSIBLY TO HELP ROOF DEFLECT RAIN FROM WALL.
- ④ SOUTH EAST FACING WALL EXTERIOR CONTAINS CHIMNEY STACK - STRUCTURE BUILT INTO QUARRY FACE. OUTSIDE EXTERIOR GROUND LEVEL IS SIMILAR TO LINTEL HEIGHT ON NORTH EAST WALL. SOME OF THE CHIMNEY SURVIVES TO ROOF HEIGHT. PHOTO NUMBERS: 512-4.
- ⑤ INTERIOR OF NORTH EAST WALL. WINDOWS ARE WIDER + LOWER ON INSIDE. EASTERN WINDOW INTERNAL DIMENSIONS: W 85cm x H 108cm. VERTICAL DIMENSION IS LOWER AS WINDOW PANEL/SILL IS LOWER. DOORWAY HEIGHT: 189cm. WEST WINDOW: W 72cm x H 114cm - AGAIN INTERIOR WINDOW IS LOWER DUE TO LOW WINDOW SILL. PHOTO NUMBERS: 509-19.
- ⑥ NORTH WEST WALL GABLE END INTERIOR. A NICHE IN WALL. H 166cm FROM GROUND + 35cm AWAY FROM NORTH CORNER. W 36cm x H 114cm. PHOTO NUMBERS: 503-4.
- ⑦ SOUTH WEST WALL INTERIOR (SEE NOTES 3). WINDOWS ARE NOT SPAYED + LINTELS AT SAME HEIGHT. PHOTO NUMBERS: 505-6.
- ⑧ SOUTH EAST WALL BY FIREPLACE. CHIMNEY STACK W 40cm x D 54cm. DISTANCE FROM EAST CORNER IS 140cm. DISTANCE FROM SOUTH CORNER IS 120cm. FIREPLACE ITSELF IS H 88cm x W 74cm. THE FIRE BASE RAISED WITH STONE BLOCKS TO 46cm. DEPTH OF FIREPLACE 59cm. FIREPLACE CONSTRUCTED WITH 3 COURSES OF DRESSED STONES SUPPORTING LARGE LINTEL ABOVE. SIMILARLY SIZED THERE IS A HOLE PLACED CENTRALLY 57cm ABOVE FIREPLACE. DIMENSIONS W 11cm x H 10cm. STONE REMOVAL FROM SOUTH SIDE OF WALL FOR SHEEP DIP ALSO HAS STONE MISSING FROM THIS WALL AS WELL AS SOUTH WEST WALL. PHOTO NUMBERS: 507-8.

GENERAL COMMENTS: STRUCTURE IS BUILT WITH DOUBLE THINNED LISTS TO FILL UP SMALL GAPS. WALLS ROUGHLY FACED WITH MORTAR VISIBLE IN PATTERNS MAINLY IN INTERIOR, FEW IN EXTERIOR. ALTHOUGH MORTAR ON EXTERIOR STONE INTERIOR FLOOR LOOKS PAVED BUT MOSTLY OBSERVED IN STONES.

STRUCTURE TO NE OF MAIN HOUSE

- ⑨ ON WEST CORNER, EARTHFAST BOULDERS. DIMENSIONS W 110cm x H 110cm x D 47cm. LARGE. THERE IS A VISIBLE CONSTRUCTED WALL BUILT, EXTENDED ALONG AT 2.72cm. (MINIMUM) WALL VISIBLE THEN GOES INTO GRASSY BANK S WEST TO NEAST. WIDTH OF NW WALL W 1.35m. THERE IS A LARGE TREE STUMP AT EASTERN END. EFFECTIVELY BLOCKS DOORWAY WHICH SUGGESTS THE DOOR HAS BEEN OUT OF USE FOR A LONG TIME. PHOTO NUMBERS: 519-7.
- ⑩ ROUGHLY BUILT WALL WITH LARGE BLOCKS OF STONE AT BASE. CONSISTENTLY SIZE & SW FACING EXTERIOR WALL. * BUT AT TOP TWO TYPES TO IT AT NW PART OF WALL HAS CAP STONES SET ON EDGE. SE WALL TOP STONES SITTING FLAT, NOT ON EDGE SUGGESTING SE PART OF BUILDING MAY HAVE BEEN ROOFED, WHEREAS, NW PART OF WALL MAY NOT HAVE BEEN ROOFED. PHOTO NUMBERS: 520-2.
- ⑪ IN THE INTERIOR OF THE SW FACING WALL, THE BOTTOM OF WALL IS CLEAR OF ANY MOSS, AS OPPOSED TO THE UPPER PART WHICH IS COVERED. THIS IS DUE TO ROCKS BEING PILED UP AGAINST THE LOWER HALF, WHICH HAVE SINCE BEEN MOVED. THIS IS ALSO EVIDENT ON ⑫ - ⑭ BUT IS NOT AS PROMINENT. H 1.40m. PHOTO NUMBERS: 525-6.
- ⑫ SEE NOTES ⑨ AND ⑪. H 0.75m. PHOTO NUMBERS: 527-9.
- ⑬ SEE NOTES ⑪. HEIGHT, 1.87m WHICH IS TALLER THAN OTHER WALLS, PRESUMABLY AS IT APPEARS TO BE BUILT INTO THE GRASS BANK. PHOTO NUMBERS: 528-4.
- ⑭ H 1.50m, SLOPING WALL FROM SE TO NW. THERE IS POSSIBLE ENTRANCE GAP IN NW CORNER OF WALL. THE GAP IS 0.71m. PHOTO NUMBERS: 530-2.

* (PERS COMM.)

Project Name						Overlays	Adjacent sheets		Title / Notes	North
Project No.										
Trench	Scale	Date	Drawn by	Checked / amended by						
ARCUS, Unit R6, Riverside Block, Sheaf Bank Business Park, Prospect Road, Sheffield, S2 3EN United Kingdom Tel: (0114) 2225106 Fax: (0114) 2797158						Plan / Section / Elevation		Drawing No.	Sheet No.	
						Other				