





NW SE



Main ceiling beam in NW ground floor room



Main ceiling beam and coffer in groundfloor central room



Moulded beams in ground floor SW room




Figure 7: Branas-uchaf, Llandrillo: Section through Ceiling Beams